ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
6

Ward Name
Thanisandra

Street ID
W0141, W0066, W0143, W0147, W0151, W0149, W0183, W

Street Name
NA, Vinayaka Lyt 2nd Crs

Significant Landmark
Police Quarters & New Shanthi Nagar

Segment No.
6/C-W0141/S120407

Total Length (m)
267.65

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	36.97	77.639346	13.073129	77.639342	13.072795	W0068	DEAD END
2	60.26	77.639147	13.073164	77.639126	13.072619	W0068	W0074
3	55.25	77.638081	13.073320	77.637979	13.072831	W0068	DEAD END
4	58.27	77.637858	13.073350	77.637754	13.072833	W0068	DEAD END
5	56.90	77.637620	13.073379	77.637538	13.072871	W0068	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvement to Roads and Drains at Police Quarters & New Shanthi Nagar in ward no 06 Byatarayanapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
3000000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvement to Roads and Drains at Police Quarters & New Shanthi Nagar in ward no 06 Byatarayanapura Sub-Division Yelahanka zone

Job No. / Work Code
006-15-000033

Work Order No.
BBMP/EE/BTP/WO/10/2016-17

Work Order Date
30/04/2016

Period of Extention
90 days

Defect Liability Period From
30/04/2016

Defect Liability Period To
29/04/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

L GANGADHAR 0.00

Phone No. **E-Mail ID**

9341260169

Field Inspection Details

Number of Trees	Any Other Information	Name
0		KRISHNAPPA
Date of Inspection	**Remarks**	
26/11/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0141, W0066, W0143, W0147,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	26/11/2016	26/12/2016	COMPLETED
SE	VASU K M	26/11/2016	26/12/2016	COMPLETED
EE	YARAPPA REDDY	26/11/2016	26/12/2016	COMPLETED
AEE	J N LOKESH	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0141, W0066, W0143, W0147,